

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 227) (Camp) AE-1) 25-24

Dated: 13/6/25

It is certified that the existing building KRS Public School ..... (name of the building or premises) at Chharora, Tehra Road Jajndawan Mathura ..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	4+1	X	X	X	X	X

The building is owned/occupied by KRS Public School ..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public works department (Name of Department/ Govt.) on 13/6/25 ..... (date of inspection) in the presence of Vijay Kumar Chahar (Manager) ..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 13/6/25 for a period of 02 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. NIL
2. NIL
3. NIL
4. NIL

Issued on 13/6/25 at Mathura by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : [Signature]

Name : Ajay Kumar

Designation : [Signature]

Name & Address of Department Office: पु.स. विभाग, जामियता, मथुरा।

66 | Page

[Signature]

Manager

Principal  
KRS Public School  
Chharora, Mathura

KRS Public School  
Chharora, Mathura

## भवन सुरक्षा प्रमाण पत्र

पत्रांक /

सेवा मे

दिनांक

मुख्य विकास अधिकारी,

मथुरा।

विषय- रिट याचिका सं० 483/2004 अवनीश महरोत्रा बनाम यूनियन ऑफ इंडिया व अन्य में पारित माननीय सर्वोच्च न्यायालय के आदेश दिनांक 13.04.2009 के अनुपालन में विद्यालय/स्कूल भवनों का निरीक्षण कर सुरक्षा प्रमाण पत्र उपलब्ध कराने के सम्बन्ध में।

संदर्भ- (1) आपका पत्र सं० 1361 दिनांक 18.10.2023।

(2) विशेष सचिव बेसिक शिक्षा अनुभाग-2 का पत्रांक 89/अरसाठ/3-2018-2041/2018 दिनांक 11.01.2019।

महोदय,

उक्त संदर्भित पत्र दिनांक 18.10.2023 के क्रम में आप द्वारा चाही गयी भवन सुरक्षा प्रमाण पत्र के क्रम में मॉगी गयी सूचना निम्नानुसार है:-

1. विद्यालय का नाम- के०आर०एस० पब्लिक स्कूल छरौरा तेहरा रोड वृन्दावन मथुरा।
2. विद्यालय तक पहुँच मार्ग- उपलब्ध है।

विद्यालय भवन का निरीक्षण करने पर पाया गया कि विद्यालय भवन भूतल, एवं प्रथम तल आर०सी०सी० से निर्मित है। प्रबन्धक एवं प्रधानाचार्य के बैठने हेतु उचित व्यवस्था है। भूतल से प्रथम तल एवं छत पर आने जाने हेतु झीना निर्मित है। विद्यालय भवन में सामान्य विद्युत व्यवस्था के अतिरिक्त आकस्मिक विद्युत व्यवस्था जेनरेटर के माध्यम से संचालित है। वर्तमान में विद्यालय भवन टिकाऊ एवं मजबूत है तथा नेशनल बिल्डिंग कोड 2005 के मानकों एवं लो०नि०वि० की विशिष्टियों के अनुरूप प्रतीत होता है।

नोट- उक्त प्रमाण पत्र की वैधता 02 वर्ष है।

( अजय कुमार )

सहायक अभियन्ता

निर्माण खण्ड-1 लो०नि०वि०

मथुरा

दिनांक 18/11/2023

पत्रांक 1003/ Camp /IAEI

प्रतिलिपि-

1. प्रबन्धक के०आर०एस० पब्लिक स्कूल छरौरा तेहरा रोड वृन्दावन मथुरा।

*Rohit*

Principal

K R S Public School  
Chharora, Mathura

*Vijay K*

Manager

K R S Public School  
Chharora, Mathura

*K18-11-23*

सहायक अभियन्ता

निर्माण खण्ड-1 लो०नि०वि०

*CSM*  
मथुरा